



DOCKET NO.: 8032-1008
APPLN NO.: 09/656,959
REPLY TO NOTICE OF ALLOWABILITY OF: NOVEMBER 30, 2004
REPLACEMENT SHEET

FIG. 1





FIG. 2



FEB 25 2005



FIG. 3
MOBILE TERMINAL






FIG. 4




FIG. 5







FIG. 6



O P E R A T I O N S
FEB 25 2005



FIG. 7A

SERVER




FIG. 7B

SERVER







FIG. 8



FEB 25 2005



FIG. 9
MOBILE TERMINAL






FIG. 10
HOME LOCATION REGISTER




FIG. 11
HOME LOCATION REGISTER







FIG. 12





DOCKET NO.: 8032-1008
 APLN NO.: 09/656,959
 REPLY TO NOTICE OF ALLOWABILITY OF: NOVEMBER 30, 2004
 REPLACEMENT SHEET

FIG. 13






FIG. 15

HOME LOCATION REGISTER






FIG. 14

SERVER

